

Job Safety Analysis

| Operating a Gasoline Po | t026 4/7/20 | | |
|---|----------------------|--|--|
| Group/Department: Maintenance Reviewed By: D Vanderleest | rerea Lage Timmer | | |
| LN# Task | Hazard | Control | |
| 1 Procedure for malfunctioning of broken equipment | or Bodily Injury | Obtain Accident Prevention Tagmark equipment "Do Not Use" – specify problem or hazard Whenever possible isolate power source so equipment cannot be used. (Lock Out- Tag Out) Notify shop and/or take equipment to shop | |
| 2 General Use Operating Edge Trimmer | Eye or Facial Injury | Wear safety goggles or full face shield to prevent eye/face injury | |
| 3 Fueling / Oiling | Fire | Never add fuel to hot or running equipment Always add fuel outdoors, ensure fuel cap is secure before use of equipment Do not add fuel near open flame, sparks or other ignition sources. Clean fuel spills immediately; do not start engine until fumes have dispersed | |
| 4 General Use Operating Edge Trimmer | Bodily Injury | Wear appropriate clothing- long pants and long sleeves or equivalent such as chaps. Keep all guards and shields in place Keep hands and loose clothing clear of all moving parts; secure loose sleeves Secure long hair | |
| Required Equipment: | Required Training | g: | |
| 1. Gloves 2. Long pants and/ or chaps | Read, understan | d, and follow manufacturer's safety instruction alified person prior to use. | |

3. Eye protection; minimally safety glasses, full face SAFESCHOOLS - Hand and Power tool Safety

SAFESCHOOLS - General Safety Orientation

shield if subject to flying debris.



Job Safety Analysis

| Operating a Gasoline Po | t026 4/7/20 | | |
|---|----------------------|--|--|
| Group/Department: Maintenance Reviewed By: D Vanderleest | rerea Lage Timmer | | |
| LN# Task | Hazard | Control | |
| 1 Procedure for malfunctioning of broken equipment | or Bodily Injury | Obtain Accident Prevention Tagmark equipment "Do Not Use" – specify problem or hazard Whenever possible isolate power source so equipment cannot be used. (Lock Out- Tag Out) Notify shop and/or take equipment to shop | |
| 2 General Use Operating Edge Trimmer | Eye or Facial Injury | Wear safety goggles or full face shield to prevent eye/face injury | |
| 3 Fueling / Oiling | Fire | Never add fuel to hot or running equipment Always add fuel outdoors, ensure fuel cap is secure before use of equipment Do not add fuel near open flame, sparks or other ignition sources. Clean fuel spills immediately; do not start engine until fumes have dispersed | |
| 4 General Use Operating Edge Trimmer | Bodily Injury | Wear appropriate clothing- long pants and long sleeves or equivalent such as chaps. Keep all guards and shields in place Keep hands and loose clothing clear of all moving parts; secure loose sleeves Secure long hair | |
| Required Equipment: | Required Training | g: | |
| 1. Gloves 2. Long pants and/ or chaps | Read, understan | d, and follow manufacturer's safety instruction alified person prior to use. | |

3. Eye protection; minimally safety glasses, full face SAFESCHOOLS - Hand and Power tool Safety

SAFESCHOOLS - General Safety Orientation

shield if subject to flying debris.



Job Safety Analysis

| Task: | | | | |
|--|---|--|----------------------|--|
| Operati | ing a Gasoline Pov | t026 4/7/20 | | |
| Group/Dep | | | | |
| Maintenan | | | | |
| Reviewed E D Vanderle | - | | | |
| | | | | |
| N# Task | | Hazard | | Control |
| | | | | If working overhead or where anything may fall on to a worker, wear a hard hat Note:(Hard hat required for all workers in area of tree work) |
| | onal Precautions for Fuel ed Engines | Injury and Fire | | Always operate in well-ventilated area Never fuel engine while running Stop engine before performing maintenance or trouble shooting Avoid contact with hot engine parts Do not place hot engine in dry vegetation |
| Gener Trimm | al Use Operating Edge ner | Inhalation of Dusts | | Wear N95 dust mask as needed |
| Gener Trimm | al Use Operating Edge ner | Foot Injury | | Wear safety boots w/ reinforced toe (steel or composite) |
| Gener Trimm | al Use Operating Edge ner | Hearing Damage | | Wear ear plugs or earmuff headset |
| Site Sa | afety | Bodily Injury from vehicles, bicyclists, etc | | Place signs, cones, barricades, caution tape, and lookouts as needed. Wear reflective safety vests |
| .0 Gener Trimm | al Use Operating Edge ner | Injury to Others | | Provide for work area safety; use cones, barricades, signs, and/or post |
| Required Ed | quipment: | | Required Training: | |
| Gloves Long pants and/ or chaps | | Read, understand, and f | nd Power tool Safety | |